


1. Determine the installation location and use the mounting bracket to mark the location of the screw holes and wiring hole. Drill a hole and pull the units wiring through. Screw down the mounting bracket using the provided screws.



2. Using the wiring diagrams below, wire the light to the units power.



3. Feed the wires back through the hole and tighten the set screws on either side of the light. Test the light.





For warranty information please visit www.itc-us.com 230 E. Lakewood Blvd. • P.O. Box 8338 • Holland • MI • 49422-8338 Phone: 616-396-1355 • Fax: 616-396-1152 • www.itc-us.com • sales@itc-us.com • 02/13/17