

Quantité de poches de sel à ajouter

Taux de sel idéal entre 2800 et 3200 ppm

Concentration actuelle de sel (ppm)	20 000 L	30 000 L	40 000 L	45 000 L	50 000 L	60 000 L	65 000 L	75 000 L	80 000 L	90 000 L	95 000 L	105 000 L	115 000 L	120 000 L	130 000 L	140 000 L	150 000 L
0	3	5	6	7.25	8.5	9.5	11	12	13.25	14.5	15.5	17	18	19	20.5	23	24
200	3	4.5	5.5	7	8	9	10.25	11.25	12.5	13.5	15	16	17	18	19	21.5	22.5
400	3	4	5.25	6.5	7.5	8.5	9.5	10.5	11.5	12	13.75	15	16	17	18	20	21
600	2.5	4	5	6	7	8	8.75	9.75	11	12	12.75	14	15	16	17	19	20
800	2.5	3.5	4.5	5.5	6.25	7.25	8.25	9	10	11.5	11.75	13	13.5	14.5	15.5	17	18
1000	2	3.5	4	5	6	6.5	7.5	8.25	9	11.5	11	12	12.5	13	14	15.75	16.5
1200	2	3	3.75	4.5	5.25	6	6.75	7.5	8.25	9	10	11	11.5	12	13	14.5	15
1400	2	2.5	3.5	4	5	5.5	6	6.75	7.5	7.5	9.5	9.5	10.5	11	11.5	13	13
1600	1.5	2.5	3	3.75	4.25	4.5	5.5	6	6.5	7.5	8	8.5	9.5	9	10.25	11.5	12
1800	1.5	2	2.5	3	3.75	4.25	4.75	5.5	5.75	6	7	7.5	8.5	8.5	9	10	10.5
2000	1	2	2.25	2.75	3	3.75	4	4.5	5	6	6	6.5	7	7.5	7.5	8.5	9
2200	1	1.5	2	2.25	2.5	3	3.5	3.75	4	4.5	5	5.5	6	6	6.5	7	7.5
2400	1	1	1.5	1.75	2	2.5	2.75	3	3.5	3.5	4	4.25	4.5	5	5.25	6	6
2600	0.5	1	1	1.5	1.5	1.5	2	2.25	2.5	3	3	3.25	3.5	3	3.75	4.25	4.5
2800	0.5	0.5	0.75	1	1	1.25	1.75	1.5	1.5	1.5	2	2	2.25	2.5	2.5	2.5	3