




Summit's Humminbird Mega Live transducer mounts must be used with the hardware provided by Summit as shown below. It is critical that the shoulder bolt is fully tightened, and the shoulder bottoms out on the transducer. **The recommended torque for the shoulder bolt is 2.5 ft-lb or 3.4 nm.**



Troubleshooting.

- If the mount feels loose or does not not “click” into position, either the rubber spacer is missing or the shoulder bolt is loose. Without the rubber spacer, the mount will never fully tighten.
- If the mount is initially tight and then loosens after use, the shoulder of the bolt did not bottom out on the mount and the bolt has loosened up.