

**Release Date:** Jun 2024  
**Software Version:** V1.96.01  
**Firmware Version:** V23.01.08

## Recommended Use

This release is recommended for all affected products listed below. It is important to keep your diagnostic tool current for optimum performance and to take advantage of all added enhancements. Please reference your user's manual on how to perform a software / firmware update on your diagnostic scan tool or code reader.

## Affected Product(s)

- INNOVA® 7111 Smart Diagnostic System

## New / Added Features & Functions

- **Add Home Screen Description**
  - Enhanced the description available on the home screen for better user guidance.
- **Improve Performance:**
  - Optimized Electronic Parking Brake (EPB) functionality for BMW vehicles.
  - Enhanced the description display for all functions to improve user experience.
- **Update Spanish Language Support:**
  - Updated and improved Spanish translations for most features to ensure accuracy and comprehensibility.
- **Vehicle Inspection:**
  - Upgraded the stabilization process for pre/post scans and combined reports for pre/post scans to ensure more reliable results and streamlined review and analysis.

## Fixes / Updates

- Other minor bug fixes and tool enhancements.

## Product Support

Please visit us at [innova.com/support](https://innova.com/support) or [pro.repairsolutions.com/Support](https://pro.repairsolutions.com/Support) for additional information.