KS kiln underfires

Condition:

Witness cones indicate that the kiln is firing approximately one cone cooler than normal

8.6b

KS kilns

Ksunderf.vsd

