



MD
FRAME

CASTING GUIDE SPACING CHART

6'0"	3 1/2"	7 1/2"	12"	17 3/8"	23 1/2"	30 1/2"	38 1/2"	--	--	--	--	--
6'6"	3 1/8"	6 7/8"	11"	15 7/8"	21 3/8"	27 3/4"	35"	43 1/2"	--	--	--	--
7'0"	3 5/8"	7 3/4"	12 1/2"	18"	24 3/8"	31 9/16"	39 7/8"	49 1/2"	--	--	--	--
7'6"	3 1/8"	6 3/4"	10 3/4"	15 1/2"	20 7/8"	27 1/8"	34 1/4"	42 1/2"	52"	--	--	--
8'0"	3 1/2"	7 1/2"	12"	17 1/4"	23 1/4"	30 1/4"	38 1/4"	47 1/2"	58"	--	--	--
8'6"	3 1/8"	6 3/4"	11"	15 3/4"	21 1/4"	27 5/8"	34 7/8"	43 1/4"	52 7/8"	64"	--	--
9'	3"	6 1/8"	9 7/8"	14 1/8"	19 1/8"	24 3/4"	31 3/8"	38 7/8"	47 1/2"	57 1/2"	69"	--
9'6"	3 1/8"	6 5/8"	10 3/4"	15 3/8"	20 3/4"	27"	34"	42 1/4"	51 5/8"	62 1/2"	75"	--
10'	3"	6 1/8"	9 3/4"	14"	18 7/8"	24 1/2"	30 7/8"	38 3/8"	46 7/8"	56 3/4"	68"	81"