



STEWART ENGINEERING

THE SUNBEAM SPECIALISTS

## Sunbeam Service Sheet No. 8

Subject: **Timing Chain Tensioner (S7 Engine)**

Date: **May 1949**

To prevent wear in the Cylinder Head and to reduce the timing chain load, the tensioner blade has been modified.

The new tensioner provides a larger area of contact with the cylinder head casting, and should be fitted to all machines undergoing major overhaul.

Small quantities of chain tensioners of the modified type will be supplied free of charge on request to the Service Department, Sunbeam Cycles Ltd., Birmingham, 11.

SERVICE DEPARTMENT  
B.S.A. CYCLES LIMITED