

Introduction - Read Me First!

This document is your instruction manual for your new SeeMeCNC® 3D printer machine. Before using your new 3D printer, thoroughly read and understand this manual for safe and effective operation of the machine.

Warning

Personal property damage, serious injury, or death can result from not following instructions or warnings in the manual or misuse of the machine.

Automatic machine can start unexpectedly. Pay close attention and keep clear while power is connected to the machine.

Adult supervision required. Children under 18 years of age require supervision.



The machine power supply is connected to AC voltage and can be hazardous. Disconnect power before servicing this machine.



The hot end of the machine can reach very high temperatures of 700F and cause serious burns. The heated print surface (heated bed) can also reach temperatures high enough to cause severe burns. Allow both to cool for 20 minutes after turning off power.



Use caution near moving parts of the machine. Keep body and loose articles clear.



Risk of Fire. Do not leave machine unattended.

Use genuine parts manufactured or designated by SeeMeCNC.

Poisonous gas, smoke, or fumes could be omitted by some materials you could use with the machine. In such case, you should install ventilation.



Choking Hazard. This machine contains small parts and can produce small parts which can be a choking hazard to children.

Keep a copy of this manual near the machine easily accessible to all operators.

Use of this machine is at your own risk.

Visit www.seemecnc.com to contact us if you have any questions.