






3

OM-FC-2
Assembly Drawing




Connecting Parts







(A)	 X6	(F)	 X6
(B)	 X6	(I)	 X36

ARROW POINT AT THE BOARD EDGE

4



Connecting Parts

(I)	 X4	(C)	 X2	(H)	 X12
(J)	 X4	(D)	 X4	(E)	 X1

ARROW POINT AT THE BOARD EDGE