

OM-HC-1

Assembly Drawing

1

Connecting Parts			
		X6	X2
	X6		X1

ARROW POINT AT THE BOARD EDGE

2

Connecting Parts			
		X16	
	X16		

ARROW POINT AT THE BOARD EDGE