



OM-HC-2
Assembly Drawing



Connecting Parts

<p>ARROW POINT AT THE BOARD EDGE</p>		<p>A X6</p>	<p>F X4</p>	<p>I X24</p>
		<p>B X6</p>		



Connecting Parts

<p>ARROW POINT AT THE BOARD EDGE</p>		<p>E X1</p>	<p>H X12</p>	<p>I X4</p>
		<p>C X4</p>	<p>D X4</p>	<p>L X4</p>