













| TOOLS   | Connecting Parts  |   |  |  |  |
|---|---|---|--|---|--|
|  |  X35 |  X40 |  X3 |   |  |
|   |  X35 |  X6  |  |   |  |
|   |  X6  |  X5  |  |   |  |
|   |  X2  |  X3  |  |   |  |


## OM-W318 Assembly Drawing







| Series No. | Specification (W*D*H) | qty | Series No. | Specification (W*D*H) | qty | Series No. | Specification (W*D*H) | qty |
|------------|-----------------------|-----|------------|-----------------------|-----|------------|-----------------------|-----|
| 1          | 1050*1050*25          | 1   | 6          | 695*300*18            | 1   | 11         |                       |     |
| 2          | 695*300*18            | 1   | 7          | 695*300*18            | 1   | 12         |                       |     |
| 3          | 695*320*18            | 1   | 8          | 750*700*25            | 2   | 13         |                       |     |
| 4          | 750*450*18            | 1   | 9          | 724*450*18            | 2   | 15         |                       |     |
| 5          | 750*450*18            | 1   | 10         | 695*694*25            | 2   | 14         |                       |     |

OM-W318-1  
Assembly Drawing


1




Connecting Parts






2



4




3






OM-W318-2  
Assembly Drawing

5




Connecting Parts




|   |  |
|---|--|
| <p>(A)  X14</p>  |  |
| <p>(B)  X14</p> |  |

6



7



8







|  |   |  |
|--|---|--|
| <p>(C)  X6</p>  | <p>(G)  X5</p> |  |
| <p>(D)  X2</p>  | <p>(H)  X3</p> |  |
| <p>(E)  X40</p> | <p>(I)  X3</p> |  |

Diagram showing the final assembly of the table with legs. Arrows indicate the direction of assembly. A hand icon points to the leg attachment.

