

DYNAVIN N7 U.S. ONLY FIRMWARE UPDATE INSTRUCTIONS – VERSION 1.0.5.7 (AMERICAN MAKES ONLY)

RELEASE DATE 10/22/19



THIS FIRMWARE VERSION is to be used with N7 units for Ford, Chevy, GM, and Jeep only.

Please read the following instructions carefully and follow each step as directed. To check the Dynavin's firmware version, swipe left on the main menu and select the "Info" icon. Look at the number on the first line. **Note: If after updating, the radio's volume is changing on its own, please contact support@dynavinnorthamerica.com or call during business hours at 559-486-4047 for the correct firmware version for your radio.**

- 1) If you have a Mustang unit purchased in 2018 with version 1.0.5.1, you may need a different firmware version. (If this firmware causes your radio's volume to change on its own, you need a different firmware version.) For the correct version, please contact us at 559.486.4047 during business hours or email support@dynavinnorthamerica.com anytime.
- 2) You will need a microSD card (do not use a card greater than 32gb) and a computer. **DO NOT USE THE iGO NAV CARD.** We recommend doing a "Quick Format" of the microSD card first. If using a PC, this can be done by right clicking the SD card location on your computer and selecting "Format...".
- 3) Go to: <https://www.dropbox.com/sh/ohfp8qvogadhkpk/AADpY9WtsII5VxLSTuZ8uGTsa?dl=0>
- 4) Once in Dropbox, you will download the files to your computer. There are two ways you can do this:

RECOMMENDED →

1. As individual files: Download each file individually. Select one file and click "Download". Do this for EACH file. Locate all 3 files and copy or drag them to the blank, formatted microSD card. **DO NOT PUT THE FILES IN A FOLDER.**

- OR -

2. As a compressed/ZIP file: Select ALL files at once and click "Download" to save directly to your computer. DO NOT save directly to the SD card. It will download as a ZIP file. Locate it and right click on the ZIP folder. Select "Extract All". Copy or drag all 3 extracted files to the blank, formatted microSD card. **DO NOT PUT THE FILES IN A FOLDER.**

- 5) Unplug any USB thumb drives, iPods, cell phones, etc. from the Dynavin USB port. Remove the iGO primo navigation card from the "NAV" slot.
- 6) Insert the firmware card into the "MMC" slot in the Dynavin, swipe left to "Info". If the firmware on your card was downloaded properly, there will be a tiny green light within the "Update Now" button on the screen. (If there is no green light, there is mostly likely something wrong with the files and you will need to reformat the card and start over.)
- 7) Select "Update Now". It will install and reboot within about 3 minutes. Ensure that power is stable and do not power off or press any buttons during this process. Once it has fully restarted, you can eject the card. If the update gets stuck and shows no progress for more than 5 minutes, please contact us.
- 8) To confirm that the update was successful, go back to the "Info" menu and check that it says **DynOS N7 1.0.5.7**.
- 9) Lastly, make sure that the correct car type is assigned. You will see this next to the DynOS version number. (MST for Mustangs) Contact us if you are not sure if the car type is correct or if you need instructions on how to change it.