

## Mustang 2015-2022 (MST2015L/H)

### Touchscreen Unresponsive

If the touchscreen is not responding, you can hold down the HOME icon button for about 10 seconds until it restarts, or you can use a paperclip to push in the round reset button labeled “RST” just to the left of the volume down button on the front panel (circled below).

(This touchscreen issue can happen when the touchscreen ribbon cable is connected AFTER the unit is powered on for the first time.)

