

# TECHNICAL SPECIFICATIONS



## FLEX SPECIAL WOOL & FOAM COMB

### DESCRIPTION

This product has a unique formulation to eliminate marks polishing pastes ; a mirror without leaving marks gloss polishing type . Its unique formulation makes it compatible with all types of paint ( polyester, polyurethane , enamels , lacquers , etc ).

### FEATURES

- Fast cutting power
- Compatible with all types of paint
- It produces a deep and perfect shine
- Easy to clean
- Leave a perfect finish
- Is silicone or wax
- Performance cars 10-15 Approx.

### PHYSICAL PROPERTIES

SOLVENTS	WATER, DERIVATIVES, LIGHT OIL
IGNITION POINT	100° C
VISCOSITY	14.000 - 20.000 cps
COLOUR	WHITE (B/N05995) GRIS (P/N05996)
CONSISTENCY	LIQUID
MINERAL	ALUMINIUM OXIDE
PERFORMANCE	10 TO 15 CARS APROX.

### APPLICATIONS

Ideal for polishing the proximal edges , handles, areas of difficult access.

### INSTRUCTIONS

- To eliminate the possibility of staining , do not apply in the sun or on a hot surface . The surface must be clean .
- Apply in small areas ( 50cmx 50cm ) and only the amount needed (TIP : two or three drops are required)
- Spread the product evenly with black mop It<sup>TM</sup> 3M Perfect Foam Polishing Pad PN05725 .
- Use a polishing low speed ( 1,400 rpm to 1,800 rpm ) with the support It<sup>TM</sup> Back Up Perfect Pad PN 05718 (TIP :The higher the speed , the greater cutting power and vice versa) .

Move the polisher linearly with enough pressure early in the process to allow the product onto the surface cut efficiently and as a shine on the surface, reducing the pressure on the stern turns freely. (TIP :..You must take care

not to burn the paint , preventing the dry product must also be careful not to overdo the time of application because it can heat the surface should monitor the borders and edges and keep the polisher constantly moving .)

TIPS : advisable to ensure the rotation of the polisher when the edges and polished edges .

### PACKING

SHORT CODE	PRODUCT DESCRIPTION	UN/BOX	MINIMUM
05725	FOAM, PERFECT LINE IR II BACK HookIt	12	01 BOX

### PRECAUTIONS

It is containing flammable solvents

Store in cool areas ( between 15 / 26 ° C)

Keep away from sources of ignition

Avoid contact with eyes.

Rotate the material according to PEPS criteria