E+motion® Lumbamed® Plus Size Chart

| Women's Sizes | 1 | 2 | 3 | 4 | 5 |
|---------------|---------|---------|----------|-----------|-----------|
| Hips (cm) | 76 - 86 | 86 - 98 | 98 - 111 | 111 - 125 | 125 - 140 |
| Men's Sizes | 1 | 2 | 3 | 4 | 5 |
| Waist (cm) | 66 - 76 | 76 - 88 | 88-101 | 101 - 115 | 115 - 130 |

c = Circumference in cm

Measure on the skin while standing using a tape measure

Size - Measure around the area: Women's - Around the hips Men's - Around the waist



