







	$\frac{1}{3}$ Turn	$\frac{1}{2}$ Turn	$\frac{2}{3}$ Turn
Required Turns	<p>Starting Position Ending Position</p> 	<p>Starting Position Ending Position</p> 	<p>Starting Position Ending Position</p> 
	<p>120 Degrees</p>  <p>ANGLE SETTING DIAL</p>	<p>180 Degrees</p>  <p>ANGLE SETTING DIAL</p>	<p>240 Degrees</p>  <p>ANGLE SETTING DIAL</p>

Important: The required turns outlined in this chart assume flat surfaces underneath the bolt head and nut.