

BHC & HOV-POD SERVICING

- Valve gap clearances checked and adjusted to correct tolerance
- Compression test – to check performance
- Up-rated spark plugs replaced
- Fuel filter replaced
- Oil filter replaced
- Air filter checked & cleaned or replaced if needed
- Engine oil changed

Integrated craft:

Mini/Mini XL / Freestyle / Beast/Beast XL / HOV-POD **BHC Engine service £220**

Includes all parts and 2 hours labour

Twin engine craft:

Coastal Pro / MACV

Includes all parts and 2 hours labour

BHC Engine service £250 Thrust engine

£230 Lift engine

We can offer on-site hovercraft servicing, please call us to discuss having a hovercraft engineer visit you to complete on-site works. We can tailor this to suit your needs and your budget

Tele: +44 (0)1304 619820 or call/Whatsapp +44 (0)7496 089537

All prices are subject to VAT (unless exporting)

