CERTIFICATE OF COMPLIANCE

Certificate Number 20190729-E364742
Report Reference E364742-A3-UL
Issue Date YYYY-MONTH-DD

Issued to: BEIJING INHAND NETWORKS TECHNOLOGY CO LTD

101,West Wing 11Th FI
No 101 Lize Central Park
Wangjing Chaoyang District

Beijing

100102 CHINA

This certificate confirms that representative samples of

INFORMATION TECHNOLOGY EQUIPMENT INCLUDING ELECTRICAL BUSINESS EQUIPMENT

See addendum Page

Have been investigated by UL in accordance with the

Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 60950-1 and CAN/CSA C22.2 No. 60950-1-07-

(Information Technology Equipment - Safety - Part 1:

General Requirements)


Additional Information: See the UL Online Certifications Directory at

https://iq.ulprospector.com for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/



CERTIFICATE OF COMPLIANCE

20190729-E364742 **Certificate Number** E364742-A3-UL **Report Reference** YYYY-MONTH-DD **Issue Date**

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Cellular Router

IR615-S-x-y-z (where x can be U, PS08, L5, L7, L3, FH20, FB78, FB53, FS18, FB13, FB23, FT43, FS39, FS08, FB58, EN00 which indicates difference wireless network systems; where y can be WLAN or NA which indicates with or without Wi-Fi function; where z can be DS or blank which indicates with or without support dual sim slot)

Bruce Mahrenholz, Director North American Certification Program

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, p contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

