

To whom it may concern

BEFORE THE INSTALLATION OF ASTEC CERAMIC INSULATING COATING SYSTEM WE HAD PROBLEMS WITH THE ROOF LEAKING BADLY AND TREMENDOUS HEAT TRANSFER TO THE STORE AND UPSTAIR OFFICES. THE HEAT WAS SO BAD THAT IT WAS IMPOSSIBLE TO WORK IN THE UPSTAIRS SECTION ON A MEDIUM TO HOT DAY.

THE EVAPORATIVE COOLING SYSTEM FAILED IN THESE CIRCUMSTANCES, AND OTHER ATTEMPTS TO WORK IN THIS AREA FAILED. THIS WAS USING FANS ETC.

THE STORE ITSELF WAS A SAUNA BATH AND STAFF HAD TO USE COLD SHOWERS ETC TO SURVIVE.

AFTER THE INSTALLATION OF THE ABOVE TREATMENT, THE UPSTAIRS OFFICES CAN BE USED IN COMFORT, EVEN ON A 40° DAY, AND THE STORE SECTION IS COMFORTABLE. SO MUCH SO THAT WE WERE ABLE TO USE CEILING FANS THAT PREVIOUSLY JUST BLEW HOT AIR AROUND. NOW THEY COOL THE AREA AS THEY ARE DESIGNED TO DO.

THE PRODUCTIVITY HAS IMPROVED MARKEDLY AND TIME LOST THROUGH STAFF BEING ABSENT ON HOT DAYS IS WAY DOWN.

THE LEAKING PROBLEMS HAVE DISAPPEARED AND IN ADDITION THE ROOF LOOKS GREAT AND I AM SURE HAS IMPROVED THE SALEABILITY OF THE PROPERTY.

THE RUST PROBLEMS WE HAD PROBABLY MEANT WE WOULD HAVE REPLACED MUCH OF THE ROOF WITHIN 12 MONTHS. IT NOW APPEARS THAT WE WILL NOT HAVE TO REPLACE ANY OF THE ROOF AND THE RUST SPREAD HAS BEEN ARRESTED. THE JOB WAS DONE WITHIN A SHORT SPACE OF TIME WITHOUT ANY PROBLEMS AT ALL AND WE WOULD CERTAINLY USE TILEBRITE FOR ANY ROOFING OR INSULATING WORK IN THE FUTURE.

YOURS FAITHFULLY D.M. SUNSTROM, MANAGING DIRECTOR,
SOUND 4 AUSTRALIA PTY LTD.



PO BOX 347
EDWARDSTOWN 5039
22 PINN st ST MARYS

PH (08) 374 0499
FAX (08) 374 0426