



CAUTION: PROTECT BALLS AND RACES FROM SAWDUST, DIRT, PAINT, ETC. SHOULD BEARING BECOME "ROUGH" FROM DIRTY RACES, FLUSH THOROUGHLY WITH HOT SOAPY WATER, RINSE, OVEN DRY AND RE-OIL.



THERE MAY BE 2 TO 4 BALLS LEFT OUT DUE TO MANUFACTURING PROCESS.

PART STAMPED WITH TRIANGLE NAME STAMP

③	3	BALLS12	BALL	1
②	2	1866	PLAIN RACE	1
①	1	1865	LOCKING RACE	1
DET	PART NUMBER	DESCRIPTION	AMT	
①	C TRIANGLE MANUFACTURING CO.			
NAME 12" LAZY SUSAN BRG. ASS'Y				
FIT	///	USED IN	///	
PLATING	E L E C T R O G A L V	DATE	7-14-8	PART NO.
MATERIAL	SEE DETAIL	DRAWN	LML	
		CHECKED	SP	
ALL DIMS. ±.020 UNLESS OTHERWISE SPECIFIED				
	SCALE	1 / 1		12C

CHANGE LEVEL
P 07-31-06