



12 x 12 FT






WQG153MS



At least need 3 people work together

REQUIRED TOOLS









A 4x

24-B037



B 4x

24-B038



B1 4x

24-B039



C 4x

24-B040




D 4x

24-B041




E 4x

24-B042



F 8x

24-B043




G 8x

24-B044



H 8x

24-B045




J 4x

24-B046




K 4x

24-B047



L 4x

24-B048



M 4x

24-B049




N 4x

24-B050



P 4x

24-B051




Q 4x

24-B052




R 4x

24-B053



S 4x



T 4x









U 1x




V 1x



O 4x

 O1 4x	 W 4x	 Z 8x	 I 4x
 X 4x	 X1 4x	 Y 4x	 Y1 4x
 Y2 4x	 Y3 4x	 Y4 4x	 Y5 4x

Bags of Screws

 M6*15 1 316x	 M6*10 2 12x	 M6*30 3 16x	 M6*55 4 8x
 M6 5 8x	 6 12x	 7 1x	 M6*35 8 12x
 4mm 9 1x	 10 1x	 rubber gasket 11 32x	

Box A		Box C		Box E	
Part #	Qty	Part #	Qty	Part #	Qty
A	4	B1	4	X	4
C	4	J	4	X1	4
F	8	G	4	Y	4
		M	2	Y1	4
		L	4	Y2	4
				Y3	4
				Y4	4
Box B		Box D		Y5	4
Part #	Qty	Part #	Qty		
B	4	D	4		
G	4	E	4		
K	4	H	8		
M	2	N	4		
R	4	P	4		
O	4	Q	4		
O1	4	S	4		
W	4	U	1		
Z	8	V	1		
I	4	Bags for screws: 1-10	1		
T	4	⑪	32		



<1>

A 4x




S 4x




M6x15

1 12x






B 4x



B1 4x



T 4x



W 4x



M6*15

1 40x



M6*55

4 8x




M6

5 8x

7

<2>







M6x15


1 24x

<3>





(J) 4x






(I) 4x




M6x15

(1) 16x

<4>







(L) 4x



M6x15


(1) 4x

<5>





(C) 4x





(Z) 8x



M6x10

(2) 12x

<6>






M6x15


1 4x

<7>





D 4x





O1 4x




M6x15


1 12x

<8>





(E) 4x



(V) 1x





(O) 4x



M6x15

(1) 16x

<9>







M6x15

1 4x

<10>







<11>


(K) 4x




M6x15

(1) 8x





(X) 4x



(X1) 4x









(R) 4x



M6x15
(1) 16x


<12>





<13>

U 1x



M 4x



7 1x




M6*30

3 8x




rubber gasket

11 8x





F 8x








G 8x



M6x15
1 56x

<14>





(H) 8x






M6x15


(1) 32x

<15>

8x




4x




4x

20



Y 4x






Y1 4x



M6x15

1 16x


<16>





<17>

Y2 4x





Y3 4x






M6x15

1 16x




4x





Y4 4x



Y5 4x



M6x15


1 24x




rubber gasket

11 16x


<18>



23



(P) 4x



(N) 4x



M6*30

(3) 8x



M6*35


(8) 8x




rubber gasket

(11) 8x

<19>





<20>

Q 4x




M6x15

1 16x





M6*35

8 4x



Tighten the
screw outside
the small window



25



<21>

6 12x



4x

