



# VE Bus BMS V2




# Lynx Smart BMS



# Non Victron Batteries



Cerbo GX Power




Temp Sensor

VE Bus  
RJ 45




VE Direct


To Positive Battery  
Terminal



HDMI / USB




# Smart Shunt Temp Sensor Wiring



*Battery monitor with auxiliary temperature sensing.*

# Smart Shunt Wiring Without Temp Sensor



*Basic battery monitor installation.*