



## DeatschWerks Technical Service Bulletin (TSB)

---

**Bulletin No:** TSB-19-05-01

**Issue Date:** May 5, 2019

**Category:** DW400 Check Valve

**Part Numbers Affected:** 9-401-XXXX, 9-402-XXXX, 9-403-XXXX

**Subject:** DW400 Fuel Pump Check Valve

---

### Description of Problem:

The DW400 Fuel Pump recent went through a product enhancement; each DW400 now comes with a check valve

### Corrective Action Suggested:

If your DW400 does not have a check valve and you would like one to be installed, DW is offering a free check valve installation service. If your DW400 is NEW (Still sealed in the package) you may exchange your product for updated DW400s with check valves. If you have already installed and used your DW400 simply ship it back to DW and our trained technical staff will install a check valve into your pump and ship it back to you free of charge.

### CUSTOMER INFORMATION

Date  Customer Name

Shipping Address

City  State  Zip Code

Phone  Email

Vehicle Year & Make  Model

### SERVICE(S) REQUESTED (check all that apply)

- New Product Exchange for DW400 with Check Valve
- Used Product Check Valve Installation

Additional information or special instructions: