









The product may pose a tip-over risk if not anchored




 				
Ax40	Bx40	Cx42	Dx7	Ex3
		 M4*16		


1.



2.



3.




Ax2

Bx2




4.



Bx2



5.




Ax4

Bx4



6.




Ax4

Bx2



7.




Ax2

Bx4




8.



Bx4



9.




Ax16

Bx16



10.



Please check the position of holes to identify panel 7 and 8.
Panel 7 - Left side. Panel 8 - Right side.

Please install the screws for the oval-shaped holes
before installing the screws for the round holes.
The same steps should be applied when
installing part C on panels 7-8.



Cx24

Dx4


Ex2



M4*16



11.



Please install the screws for the oval-shaped holes before installing the screws for the round holes.

Cx18 Dx3 Ex1

