



Bakeneko60

Manufacturing Standards

The following items are normal manufacturing standards for this product and are expected to come with your purchase.



Ejector Pin Marks

Imprints caused by the ejector pins that show on the inside of the case. Not visible when fully assembled.



Weld Lines

Line above the USB-C port that looks like a hairline scratch or crack. Common mark on injection molded pieces. Noticeable in harsh lighting only.



Pressure Marks

Several areas may exhibit slight discoloration due to pressure from the injection molding process. This is normal for polycarbonate.