

# DTF TRANSFER

## Heat Press Instructions

All transfers are Hot or Cold peel and can be peeled as soon the heat press process is complete. For any other materials such as paper, wood, leather, etc test each product with your heat press to obtain the best results.

### Electric Heat Press

PRODUCT	TEMPERATURE	PRESSURE	HEAT PRESS TIME
100% COTTON	320 DEGREES	MAX PRESSURE	10 SECONDS
100% POLYESTER	285 DEGREES	MAX PRESSURE	3 SECONDS
50/50 OR TRI BLEND	285 DEGREES	MAX PRESSURE	7 SECONDS

### Air Pneumatic Heat Press

PRODUCT	TEMPERATURE	PRESSURE	HEAT PRESS TIME
100% COTTON	320 DEGREES	MAX PRESSURE	10 SECONDS
100% POLYESTER	285 DEGREES	MAX PRESSURE	3 SECONDS
50/50 OR TRI BLEND	285 DEGREES	MAX PRESSURE	7 SECONDS

