


FACE MASK FLAT MEASUREMENTS

	MEASURING CHART	SMALL	LARGE
	1. CENTER SEAM	5"	6"
	2. SIDE TO SIDE	8.5"	9.5"
	<p>LAY MASK FLAT TO MEASURE. FLEXIBLE VINYL TAPE MEASURE IS BEST FOR ACCURATE MEASURING.</p> <p>ALLOW FOR +/- 0.25" TOLERANCE FOR ALL MEASUREMENTS.</p>		
