




Ten perimeter screw holes (shown as black dots).

Options shown for tug bar mount holes and pickup mounting holes (grey dots).



Option: Tug Bar Mounts

Option: Pickup Mounting Holes