



Ten perimeter screw holes (shown as black dots), used on early 50s P-bass models and numerous reissues.
Options shown for tug bar mount holes and pickup mounting holes (grey dots).

