


INSTALLATION INSTRUCTIONS

CAUTION:

UNPACK PRODUCT WEARING GLOVES. BEFORE INSTALLATION, SHUT OFF MAIN ELECTRICAL SUPPLY TO JUNCTION FROM FUSE BOX.


REMOVE ALL PACKAGING FROM PRODUCT AND CHECK ALL PARTS ARE INCLUDED. IF ANY DAMAGE OR DEFECT IS FOUND, DO NOT INSTALL. RETAIN ALL PACKAGING MATERIAL UNTIL INSTALLATION IS COMPLETE AND APPROVED.



STEP 1:

MARK FIXING HOLES


- ALIGN SPOT DIFFUSER (B) OVER RECESSED CEILING SPOT LIGHT.
- MARK THROUGH THE THREE FIXING HOLES ONTO THE CEILING SURFACE TO IDENTIFY FIXING POINTS.



STEP 2:

DRILL FIXING HOLES AND INSERT RAWL PLUGS


- DRILL THREE FIXING HOLES INTO CEILING USING SUITABLE DRILL BIT TO SUIT SIZE OF SCREWS PROVIDED
- **CAUTION:** ENSURE NOT TO DRILL THROUGH ANY SERVICES INCLUDING ELECTRICAL AND WATER CONCEALED BY THE CEILING SURFACE.
- FULLY INSERT RAWL PLUGS (A) SUITABLE FOR FITTING WEIGHT, CEILING STRUCTURE AND WALL FIXINGS PROVIDED.



STEP 3:

INSTALL SPOT DIFFUSER TO CEILING


- POSITION FIXING (B) OVER RECESSED SPOT LIGHT ALIGNING FIXING HOLES.
- INSERT CEILING FIXINGS (C) PROVIDED AND TIGHTEN USING FLAT HEAD SCREW DRIVER TAKING CARE TO AVOID SCRATCHING DECORATIVE FINISH.
- **CAUTION:** DO NOT OVER TIGHTEN DUE TO RISK OF DEFORMING FITTING AROUND FIXING HOLES.



STEP 4:

RESTORE POWER

- RESTORE POWER TO THE MAIN ELECTRICAL SUPPLY.



FOR MORE INFORMATION PLEASE CONTACT CUSTOMER SERVICES: