

# SPLUGEN BRAU



## Assembly Instructions for Splugen Brau

1. Pass wire through canopy and mounting plate as shown.
2. Tie strain relief knot as shown in detail "A" at desired length. Make electrical connections.
3. Secure mounting plate to junction box.
4. Secure canopy in place with set screw.

Lamp: 100 Watt (Max) 120 Volt A-19 silver bowl

NOTE: Retain this sheet with warranty card for replacement part numbers.

U.L. LISTED



**FLOS**  
INCORPORATED