




DNOX3.1 - BMW E70 Tank Unit OEM vs Bosch Service Strategy

- ▶ Bosch PN F-01C-190-075 / BMW 16-19-7-244-138
 - Consists of the Tank and Heating Pot Assembly
- ▶ The cause of failure is not typically associated with the tank, but only with the Heating Pot
 - In these cases, Bosch recommends Heating Pot Kit PN F01C600251



Pos.2 LOCKING KIT / Verschlussatz
ADDED SEPARATELY IN BAG / lose in Verpackung beigestellt



Pos.5 FASTENER KIT / Befestigungssatz
5 PIECES / 5 Stuecke
ADDED SEPARATELY IN BAG / lose in Verpackung beigestellt



DNOX3.1 - BMW E70 Tank Unit

Complete Tank Unit Assembly

Supply Module

Heating Pot

