



ADU Pre Made Loom Pinout

Connector:	Sensor Supply	Connector:	MAIN
Pin	Description	Pin	Description
1	5V	1	SWITCHED 12V
2	5V	2	BATTERY 12V
3	5V	3	POWER GND
4	SENSOR GND	4	-
5	SENSOR GND	5	CAN1 H
6	SENSOR GND	6	CAN1 L
		7	CAN2 H
		8	CAN2 L
Connector:	GPS		
Pin	Description		
1	POWER GND	Connector:	Comms
2	CAN1 H	Description:	CAN to USB
3	CAN1 L	Connector:	Logger
4	SWITCHED 12V	Description:	USB & Logging
Connector:	LW3	Connector:	LW4
Pin	Description	Pin	Description
WHT	FRQ/DGT D8	WHT	FRQ/DGT D7
GRY	SENSOR GND	GRY	SENSOR GND