



- ① Cable - 5m (M12 to M8)
- ② Cable - UTP (RJ45 to RJ45)
- ③ Cable - USB (USB A to USB C)
- ④ OnRobot Eye Box
- ⑤ Power Supply (EU,US,UK,AS)
- ⑥ USB Stick
- ⑦ Calibration Plate
- ⑧ Camera External Mount
- ⑨ Camera Robot Mount
- ⑩ Cable Holder
- ⑪ Screws for Dual QC\*  
\* Dual QC sold separately
- ⑫ Screws for QC\* or HEX QC\*
- ⑬ Screws for Calibration Sheet
- ⑭ Screw for Camera Locking Pre-mounted
- ⑮ Keys: T20/HEX 2.5 & 3 mm
- ⑯ Landmark
- ⑰ Terminal Blocks
- ⑱ Cable Straps
- ⑳ Lens Cleaning Cloth