


*Content varies based on tool combination - See outside sticker



① Quick Changer
Robot Side

② Quick Changer - I/O
Robot Side

③ Quick Changer
Tool Side

④ Torx key T30

⑤ Screw M6x8mm

⑥ Pin Ø6x10mm

⑦ Torx key T8

⑧ Cable strain relief

⑨ Screw M2,5x5mm