



## Copper Arthritis Gloves

### COPPER INFUSED COMPRESSION GLOVES



## SIZE REFERENCE

Method of measuring palm circumference:  
Please circle the palm with a soft ruler and measure the length of the palm circumference(as shown in the figure).  
After measuring your palm circumference,choose the appropriate size according to the scale table.

	Size	Cm
	S	13~17
	M	17~20
	L	20~24

Manual measurement, 1~2cm error, this is normal