



Windows 7/ Windows 10 Calibration

Magic Touch GR Touch Frames


1. Go to Control Panel. You can search for it by using Window's search bar.
2. Go to Hardware and sound.




3. Go to Tablet PC Settings.



4. Click on "Setup" to set touch screen to the correct monitor.



5. Click on “Calibrate.”



6. Go through each point accordingly.

- a. Best to insert your finger and touch quickly for each point.
- b. After each touch, back your finger out of the frame
 - i. For example, you cannot touch the first point and drag your finger to the next point.
- c. Continue until calibration is complete

If you have further questions, contact us at support@tycotouch.com or call 469-914-0021