


* No Flux contained.

A5009

Replacement Parts



Simply push the shaft for a generous coating of flux



No. FS210-82 (Flux container)

Brush-tip with a cap (5 pcs)