

# PARISI TAPWARE

CARTRIDGE REPLACEMENT



Read the complete instructions carefully to ensure that replacement proceeds smoothly.

Check the water pressure rating, Do Not Replace Cartridge **if exceed 500kPA**. Contact Builder or Plumber!!

**Caution:** Before beginning your repair, always turn OFF the water supply. Then turn your tap ON to be sure the water is completely off and to relieve water pressure. If there are no shutoffs nearby, you would need to shut the water off from the main supply (off to the home).

<p>Handle</p> <p>Dome Sleeve</p> <p>Grub Screw</p> <p>Cap</p> <p>Cartridge Nut</p> <p>Rubber O-rings</p> <p>Cartridge</p> <p>Body</p> <p>Aerator</p>	<p>Recommended tools</p> <p>Hex Key Set</p> <p>Adjustable Wrench</p> <p>Needle Pliers Offset</p>	
<p>1 Cartridge Replacement Steps</p> <p>Locate the cap either at the front or back of handle and remove it.</p>		
<p>2</p> <p>loosen the grub screw to remove handle</p>	<p>3</p> <p>Lift off the dome sleeve using hand to access cartridge</p>	<p>4</p> <p>Unscrew cartridge nut by Plier or wrench.</p>
<p>5</p> <p>Remove old cartridge, check for debris inside the body.</p>	<p>6</p> <p>Install new cartridge</p> <p>Align cartridge pins with holes inside the body and ensure seal placement.</p> <p>7</p> <p>Turn ON the water &amp; check for leakage.</p> <p>Reverse the steps that you followed to remove the cartridge to re-install parts.</p> <p><b>NOTE:</b> Do not overtightened the cartridge.</p>	

## Basin Mixer Spare Part Code

Product Name	Product Code	Cartridge Code						Aerator Code
		X1A029N	X1A079N	X1A080N	X1B029N	X1B030N	X1F029N	
ABC	HA.01-1H				●			SP.40.2258.010
ELLI II	E2.01-1H			●				SP.40.8060.010
ENVY II	P2.01-1H		●					SP.44.3360.010
QUASAR II	Q2.01-1H			●				SP.40.8060.010
ELLI	PE.01-1H				●			SP.40.2258.010
ENVY	PP.01-1H	●						SP.44.3251.010
PLAY	HP.01-1H	●						SP.44.3251.010
QUAD	HQ.01-1H				●			SP.40.2258.010
QUASAR	PQ.01-1H				●			SP.40.2258.010
FLOAT	FL.01-1H						●	SP.40.8060.010
LOOM	LO.01-1H						●	SP.40.8060.010
T2DO	T2DO.01-1H		●					SP.44.3360.010
TONDO II	T2.01-1H		●					SP.44.3360.010
SLIM	KL.01-1H			●				SP.40.8060.010

## Kitchen Mixer Spare Part Code

ELLI	PE.07-1HR					●		SP.44.3251.010
ELLI	PE.07-1HRO	●						SP.18.20013.7
ELLI	PE.07-1HS					●		SP.44.3251.010
ENVY	PP.07-1HR					●		SP.44.3251.010
ENVY	PP.07-1HRO	●						SP.18.20013.7
ENVY	PP.07-1HS					●		SP.44.3251.010
QUASAR	PQ.07-1HS	●						SP.44.3251.010

**Recommended tightening torque:**

6-8Nm for X1A029N, X1A079N, X1A080N  
 12-13Nm for X1B029N, X1F029N & X1B030N

Basin/Kitchen Mixer with same parent code uses the same cartridge:

For example; Basin Mixer **P2.01-1H**, **P2.01-1H60** and **P2.01-1H120** shared the same cartridge.