



E I C H H O L T Z

105500 DRESSING MIRROR CAPRI

ASSEMBLY INSTRUCTION

**PARTS**

1x	6x	6x	1x	6x	1x
(A)	(B)	(C)	(D)	(E)	(F)

12x	12x	1x	2x	2x	1x
(G)	(H)	(I)	(J)	(K)	(L)

**1**

HOLD

**2**

HOLD

PULL

**3**