


---

## HORIZONTAL TEMPLATE



---


## SUBLIMATION INSTRUCTIONS

- RECOMMENDED PRESS: FLAT
- TIME: 75 - 95 SECONDS
- TEMPERATURE: 400 F (204 CELSIUS)
- PRESSURE: MEDIUM
- TAPE ON 2 SIDES WITH HEAT TAPE
- PRESS PLATE WITH SUBSTRATE FACING UP
- PLACE BETWEEN PARCHMENT PAPER TO PREVENT BLEED
- LET METAL COOL BEFORE PEELING PAPER (HELPS WITH GHOSTING)

---

## VERTICAL TEMPLATE

4.125"  
4.00"  
3.85"



6.125"  
6.00"  
5.85"

---

## SUBLIMATION INSTRUCTIONS

- RECOMMENDED PRESS: FLAT
- TIME: 75 - 95 SECONDS
- TEMPERATURE: 400 F (204 CELSIUS)
- PRESSURE: MEDIUM
- TAPE ON 2 SIDES WITH HEAT TAPE
- PRESS PLATE WITH SUBSTRATE FACING UP
- PLACE BETWEEN PARCHMENT PAPER TO PREVENT BLEED
- LET METAL COOL BEFORE PEELING PAPER (HELPS WITH GHOSTING)