

32P
TO
48P

CONVERSION
CHART



32P	48P	CLOSEST	32P	48P	CLOSEST
10	15.000002	15	45	67.500007	
11	16.500002		46	69.000007	69
12	18.000002	18	47	70.500007	
13	19.500002		48	72.000007	72
14	21.000002	21	49	73.500007	
15	22.500002		50	75.000008	75
16	24.000002	24	51	76.500008	
17	25.500003		52	78.000008	78
18	27.000003	27	53	79.500008	
19	28.500003		54	81.000008	81
20	30.000003	30	55	82.500008	
21	31.500003		56	84.000008	84
22	33.000003	33	57	85.500009	
23	34.500003		58	87.000009	87
24	36.000004	36	59	88.500009	
25	37.500004		60	90.000009	90
26	39.000004	39	51	76.500008	
27	40.500004		62	93.000009	93
28	42.000004	42	63	94.500009	
29	43.500004		64	96.00001	96
30	45.000005	46	65	97.50001	
31	46.500005		66	99.00001	99
32	48.000005	48	67	100.50001	
33	49.500005		68	102.00001	102
34	51.000005	51	69	103.50001	
35	52.500005		70	105.00001	105
36	54.000005	52	71	106.50001	
37	55.500006		72	108.00001	108
38	57.000006	57	74	111.00001	111
39	58.500006		75	112.50001	
40	60.000006	60	76	114.00001	114
41	61.500006		77	115.50001	
42	63.000006	63	78	117.00001	117
43	64.500006		79	118.50001	
44	66.000007	66	80	120.00001	120