

Rubber Grommet Placement in WM-1500-2500CD units

At the back left corner, on the underside, there is a circular cutout for the head of the power cord to be pulled through. Also, the back section is where the hot exhaust is blowing out from.

Upon coming to the end of the power cord's slack, there is a rubber grommet that would need to be seated properly to fully seal the cutout, and not allow the hot air to seep back into the space you are trying to keep chilled.

With the rubber grommet out of place, all the hot air is allowed to blow back into your cabinet.

Please check and confirm if this rubber seal is in place. See photos below for reference.







