ORCA SLIP – 252201, 2522011, 252201115 High Slip / Semi-Permanent Mold Release Agent



Orca Slip Mold Release Agent

ORCA SLIP uses a cross linking polymer technology which reduces user costs by improving the mold treatment process. It combines mold release with multiple pulls, high slip qualities and durability when molding intricate parts. ORCA SLIP has a short cure time for fast turnover and does not require a sealer. It utilizes a proprietary release polymer blended into a rapidly evaporating carrier. This carrier functions to dissolve the release agent, dispersing it uniformly throughout the mold surface while preventing premature buildup. ORCA SLIP can be used for both gel-coated and non-gel-coated molding applications including: hand lay-up, mandrel molding, solid surface, casting, compression molding, polymer concrete, resin transfer, extrusion, encapsulation and pressing. It may be utilized for most thermoset and thermoplastic resins and gel coats such as polyester, DCPD, epoxy, vinyl ester, melamine, phenolics, PU, ABS, nylon, PVC, PP, PE, and acrylic.

ADVANTAGES

- EXTRA HIGH SLIP PROPERTIES FOR DIFFICULT RELEASES.
- SUPERIOR PERFORMANCE WITHOUT THE USE OF A SEALER
- SHORT CURE TIME FOR FAST TURNOVER
- ALLOWS MULTIPLE MOLDING CYCLES
- ECONOMICAL WITHOUT SACRIFICING PERFORMANCE
- APPLIES QUICKLY AND EASILY
- EXCELLENT FOR INTRICATE MOLD CONFIGURATIONS

APPLICATION:

- 1. Thoroughly clean the entire mold surface from all contaminants such as previous release agents, sealers, oils, and waxes utilizing ORCA CLEAN.
- 2. Apply ORCA SLIP with a clean lint free cotton cloth in circular motion uniformly covering a few square feet of the mold surface at a time. Avoid pooling or over application.
- 3. When ORCA SLIP begins to flash off, wipe off any excess with a clean, dry lint free cloth.
- 4. Allow 5 minutes between coats before applying the next coat.
- 5. Apply a total of 6-8 coats on a new or repaired mold. Apply a total of 4-6 coats on a seasoned mold.
- 6. Once final coat of ORCA SLIP is applied and cured, wait for an additional 15 minutes before beginning molding operations.
- 7. Reapply 1 coat of ORCA SLIP as needed when difficulty releasing occurs.

SUGGESTED FIRST AID:

Eye contact: Flush eyes with large amounts of water. If symptoms persist get medical attention. Skin Contact: Wash affected area with soap and water. If symptoms persist get medical attention. Inhalation: Remove person to fresh air. If symptoms develop get medical attention.

Health: 2 DANGER! Flammable. Harmful or fatal if swallowed. May cause blindness. Vapor harmful.

Flammability: 3

Physical Hazard: 1 Refer to SDS and warnings prior to use. For Chemical Emergency, Spill Leak Fire Exposure

Personal Protection: X or Accident Call CHEMTREC Day or Night. International 703-527-3887

The information herein is general information designed to assist customers in determining whether Orca products are suitable to their applications. Orca products are intended for sale to industrial and commercial customers. We require customers to inspect and test our products before use and to satisfy themselves as to contents and suitability for their specific applications. Nothing herein constitute any warranty express or implied, including any warranty of merchantability or fitness for a particular purpose, nor is any protection from any law or patent to be inferred. The exclusive remedy for all proven claims is limited to replacement of our materials and in no event shall we be liable for special, incidental or consequential damages.