Need jetting help? Contact our Technical Support Team! Phone: 254-848-4300 EXT. 111

Email: techsupport@nitrousoutlet.com

ALCOHOL: .178 N20 and .310 FUEL SOLENOID						
HP	N20	FUEL 5PSI	FUEL 7PSI	FUEL 10PSI	FUEL 45PSI	FUEL 55PSI
100	.018	.017	.016	_		
150	.020	.022	.020	.018	.014	.012
200	.026	.024	.022	.021	.014	.014
250	.029	.028	.025	.023	.016	.016
300	.032	.030	.028	.025	.018	.018
350	.035	.033	.030	.028	.020	.018
400	.038	.036	.033	.030	.021	.020
450	.041	.038	.035	.032	.022	.021
500	.044	.043	.039	.036	.025	.023
550	.046	.045	.041	.037	.026	.025
600	.050	.047	.044	.040	.028	.026
650	.054	.049	.045	.041	.029	.028
700	.058	.056	.052	.046	.032	.030
750	.060	.058	.054	.048	.033	.032
800	.064	.062	.058	.054	.036	.035





JC14@N20081220

(254) **848-4300**



NEED MORE JETS? VISIT NITROUSOUTLET.COM 305 S. 28th St. | Waco, TX 76710 | sales@nitrousoutlet.com

KRAKEN RACE GASOLINE & E85 JETTING CHART

Attention: Jetting may vary from application to application. We strongly suggest tuning by reading spark plugs and with a wide band 02 sensor to make sure your air fuel mixture is correct.



G/	420FINE	::.1/8 N	zu and	.310 FUE	L SULEN	עוט
HP	N20	FUEL 5PSI	FUEL 7PSI	FUEL 10PSI	FUEL 45PSI	FUEL 55PSI
100	.018	.015	.014		_	_
150	.020	.019	.017	.016	.012	.010
200	.026	.021	.019	.018	.012	.012
250	.029	.024	.022	.020	.014	.014
300	.032	.026	.024	.022	.016	.016
350	.035	.029	.026	.024	.017	.016
400	.038	.031	.029	.026	.018	.017
450	.041	.033	.030	.028	.019	.018
500	.044	.037	.034	.031	.022	.020
550	.046	.039	.036	.032	.023	.022
600	.050	.041	.038	.035	.024	.023
650	.054	.043	.039	.036	.025	.024
700	.058	.048	.044	.040	.028	.026
750	.060	.050	.046	.042	.029	.028
800	.064	.054	.050	.046	.031	.030

E85: .178 N20 and .310 FUEL SOLENOID						
HP	N20	FUEL 5PSI	FUEL 7PSI	FUEL 10PSI	FUEL 45PSI	FUEL 55PSI
100	.018	.017	.016	_	_	_
150	.020	.021	.019	.018	.014	.012
200	.026	.023	.021	.020	.014	.014
250	.029	.026	.024	.022	.016	.016
300	.032	.029	.026	.024	.018	.018
350	.035	.032	.029	.026	.019	.018
400	.038	.034	.032	.029	.020	.019
450	.041	.036	.033	.031	.021	.020
500	.044	.041	.037	.034	.024	.022
550	.046	.043	.040	.035	.025	.024
600	.050	.045	.042	.039	.026	.025
650	.054	.047	.043	.040	.028	.026
700	.058	.054	.048	.044	.031	.029
750	.060	.056	.052	.046	.032	.031
800	.064	.060	.056	.052	.034	.033





JC14@N20081220