

PLEASE NOTE

The mercury in the UV tube(s) in this lamp was replaced with an amalgam (a blend of mercury with other metals). Since the amalgam uses less mercury, it is more environmentally friendly.

The amalgam ball rolling around inside the UV tube is normal, and does not indicate that the tube is damaged or defective.



www.Spectro-UV.com

4 Dubon Ct., Farmingdale, NY 11735
866-230-7305