

## **80 Series Parts Manual**





04/21 which is known to the state of California to cause cancer and birth defects or other to cause cancer and birth defects or other reproductive harm. For more information go to www.P65warnings.ca.gov.

For assistance, contact SARGENT at 800-727-5477 or www.sargentlock.com

Experience a safer and more open world

Copyright @ 2017-2021, SARGENT Manufacturing Company. All rights reserved. Reproduction in whole or in part without the express written permission of SARGENT Manufacturing Company is prohibited.


| 12-(FM, HC, HC4) | 8706 | 8710 | 8713 | 8715 |
|------------------|------|------|------|------|
| (FM, HC, HC4)    | 8728 | 8740 | 8743 | 8746 |
|                  | 8762 | 8763 | 8773 | 8774 |



| Function        | Assembly No. | Description   | Sellable |
|-----------------|--------------|---|----------|
| (All Functions) | 97-2003      | Top Case Assembly<br>Manufactured Before 11/11/2002 | Yes      |
|                 | 68-4561      | Top Case Assembly<br>Manufactured After 11/11/2002  | Yes      |

| ltem | Assy No. | Part No.                | Description              | Qty | Sellable |
|------|----------|-------------------------|--------------------------|-----|----------|
| 1    |          | 97-0084                 | Top Cover*               | 1   | Yes      |
| 2    | N/A      | 68-3905                 | Screw Pack (B)*          | 1   | Yes      |
| 3    | -        | 97-0079                 | Top Case Filler          | 1   | Yes      |
| 4    |          | 01-1490                 | #4-40 x 3/8 PH Pan MS    | 2   | Yes      |
| 5    |          | 97-0579 Spring, Torsion |                          | 1   | Yes      |
| 6    |          | 97-0065                 | Pin, Latch Release Lever | 1   | Yes      |
| 7    | 97-2003  | 01-0695                 | Spirol Pin               | 1   | Yes      |
| 8    |          | 97-0270                 | Top Reinforcement        | 1   | Yes      |
| 9    |          | 97-2046                 | Top Slide Assembly       | 1   | Yes      |
| 10   |          | 68-1155                 | Latch Release Lever      | 1   | Yes      |
| 11   |          | 97-0080                 | Chassis                  | 1   | Yes      |
| 12   |          | 01-0476                 | Snap-In Nyliner          | 1   | Yes      |
| 3    | 68-4561  | 97-0079                 | Top Case Filler          | 1   | Yes      |
| 4    |          | 01-1490                 | #4-40 x 3/8 PH Pan MS    | 2   | Yes      |
| 5    |          | 97-0579                 | Spring, Torsion          | 1   | Yes      |
| 6    |          | 97-0065                 | Pin, Latch Release Lever | 1   | Yes      |
| 7    |          | 01-0695                 | Spirol Pin               | 1   | Yes      |
| 8    |          | 97-0761                 | Top Reinforcement        | 1   | Yes      |
| 9    |          | 68-4560                 | Top Slide Assembly       | 1   | Yes      |
| 10   |          | 68-1665                 | Latch Release Lever      | 1   | Yes      |
| 11   |          | 97-0080                 | Chassis                  | 1   | Yes      |
| 12   |          | 01-0476                 | Snap-In Nyliner          | 1   | Yes      |
| 13   |          | 670T                    | Top Rod                  | 1   | Yes      |
| 14   | N/A      | 97-0020                 | Rod Guide*               | 1   | Yes      |
| 15   | <u> </u> | 659                     | Strike Pack              | 1   | Yes      |

\*Specify Finish



The warranty on SARGENT® products becomes void if the product is modified in any way, regardless of whether the modification causes or contributes to any alleged defect. If a SARGENT product is modified it may no longer meet industry certification and quality control standards applicable to the original product and is no longer a genuine SARGENT product.

Experience a safer and more open world

Copyright © 2017-2021, SARGENT Manufacturing Company. All rights reserved. Reproduction in whole or in part without the express written permission of SARGENT Manufacturing Company is prohibited.