19' Crystal Branch Tree Instructions

Parts Included:

- 2 Pole Sections
- 8 Top Branches
- 8 Middle Branches
- 8 Bottom Branches
- 80 Total Light Strands (2 on each top branch; 3 on each middle branch; 5 on each bottom branch)
- 6,480 Total Bulbs

NOTE: Ladder required for assembly.

Instructions:

- Attach the top and bottom pole sections by lying them on their sides* and aligning the notches on both pieces.
 - *We recommend propping one end of the pole up to make this process easier.
- **2.** Bolt the sections together using two 3/8" x 4 $\frac{1}{2}$ " screws.
- **3.** Lay the tree base on its side* and insert the pole into the base.
 - *Again, we recommend resting the base on another surface to prop it up.
- **4.** Stand the base and pole up and set it in its intended location.











- 5. Select a bottom branch and slide it into the <u>bracket</u> at the base, making sure to align the <u>slot</u> in the top of the branch over the tab in the middle of the pole.
- 6. Select a middle branch and slide it into the top of the bottom branch. Again, be sure to align the slot at the top of the branch over the tab at the middle of the pole.
- 7. Select a top branch and slide it into the top of the middle branch in the same fashion.
- 8. Plug the male connectors at the base of the top branches into the female connectors at the top of the middle branches.*
 - *Polarity is very important in these connections so make sure to properly align the prongs.

Repeat in this fashion for the connectors on the middle and bottom branches. Keep in mind that the middle branches plug into the extender cable that is run along the bottom branch.











- Plug your tree into a 110V power source to ensure the branches are properly connected and lit before moving forward. If the bottom branch is lit but the top is not, make sure the male and female connectors are properly aligned.
- 10. Repeat steps 5-9 with the remaining branches. The connectors at the base* of the tree can be moved around to better reach each branch.

*You should have 16 connections when complete – 8 bottom branches and 8 extender cables.

11. Once complete, fold the cords up the support pole and secure with cable ties for a neat appearance.

NOTE: The base panel that says Dekra-Lite is removable for easy access to the transformers.

