

V-Burst

Set-up Instructions

Basic Assembly

- 1) Spread collapsed display out in all four directions - fabric graphic facing up
- 2) Connect apposing J-hooks around perimeter of display
- 3) Stand display up and connect remaining center J-hooks from behind
- 4) To break down, repeat steps in reverse
Note: make sure all J-hooks are disengaged before collapsing display

